भारत सरकार /GOVERNMENT OF INDIA
रेल मंत्रालय / MINISTRY OF RAILWAYS
रेलवे बोर्ड / RAILWAY BOARD

No. 2005/M(N)/204/1 Vol.III

New Delhi, Dated: 20.05.2016

The Chief Mechanical Engineers
All Zonal Railways

Sub: Meeting of Rail Cement Coordination Group (RCCG) in Rail Bhawan.

A meeting of Rail Cement Co-ordination Group (RCCG) was held at Railway Board on 08.01.2016. During discussion, the Cement Manufacturers Association (CMA) highlighted the quality of wagons affecting despatch of cement from sidings.

In this regard, Zonal Railways are requested to take action as per instructions issued vide letter no. 2005/M(N)/204/1 Vol. III dated 19.10.2015. Accordingly, the identified doors of BCNHL wagons are to be repaired under RSP.

Damaged doors of other designs, if found, are to be replaced or repaired by Open Line Depots and Workshops under Revenue. For this purpose, Zonal Railways should arrange adequate spares and plan for building up capacity so that damaged doors are replaced/repaired instantly.

20/5/16

(Rajesh Kumar)
Dir. Mech. Engg. (Frt.)
Railway Board

CC/-
1. EDFM/Railway Board.
2. Executive Director Standards Wagon/ RDSO-*for kind information please.*

Please advise
24/5/2016