भारत सरकार Government of India

रेल मंत्रालय Ministry of Railways

रेलवे बोर्ड Railway Board

No.:2015/M(N)/951/66 New Delhi, dated: 03.11.2015

**The Chief Mechanical Engineers**
**All Indian Railways**

**Sub: Moisture control in Stationary Compressors**

The position of stationary compressors collected from Railways recently indicate that a number of them are not equipped with moisture control devices. Stationary Compressors being used over Indian Railways for wagon maintenance/testing activities need to have provision of an equipment for moisture separation/moisture trapping/air drier to ensure that moisture ingress doesn't take place in brake system of wagons.

It is, therefore, requested that Railways may ensure the availability of equipment for moisture separation/moisture trapping/air drier in stationary compressors used by them for wagon maintenance / testing activities by 31.12.2015 under advice to this office.

03/11/15

**(Anirudh Kumar)**
**Dir. Mech. Engg. (Frt.)**

Please issue 4/11/2015

Issue with Enclosure 04/11/15