भारत सरकार Government of India
रेल मंत्रालय Ministry of Railways
रेलवे बोर्ड Railway Board

No.2017/M(N)/951/32 **New Delhi, dated: 31 .01.2019**

The Principal Chief Mechanical Engineers
All Indian Railway (Except SER)

Sub: Repair of defective centre sill damaged wagons.
Ref: Board's letter No. 2017/M(N)/951/32 dated 19.07.2018.

Vide Board's letter of even no. dated 19.07.2018, procedure of repair for crack in centre sill in BOXNHL and BCNHL wagons has been advised.

It is further requested that all the wagons available with Railways with centre sill crack are to be tackléd on the concerned Railway Workshop or the associated workshop.

Repair of accumulated wagons with centre sill crack at SER shall be undertaken at KGP workshop in phased manner.

DA: As above.

(Ajay Nandan)
Exe.Dir. Mech. Engg.(frt.)
Railway Board

Copy to: The Principal Chief Mechanical Engineer/SER- This is in reference PCME/SER's D.O. No. M2/W-120/Wagon Maintenance/06 dated 09.01.2019.