9.5

GOVERNMENT OF INDIA / BHARAT SARKAR
MINISTRY OF RAILWAYS / RAIL MANTRALAYA
(RAILWAY BOARD)

No. 2007/SIG/Non-Gaz/1/Norm

New Delhi 19.06.2017

CSTEs
All Indian Railways

Sub: Long duration signaling failures in Railways.

During discussions on the signal incidences reported to Railway Board, it has been revealed that many SSEs (Signal) have not been provided with transport facility for men and material.

Guidelines were issued vide Railway Board's letter No.2007/SIG/ Non-Gaz/1/Norm dated 16.08.2010 to hire pick-up vans for transporting men and material to improve mobility.

Immediate action may kindly be taken for providing pick-up vans for better mobility which will enable quick movement of men and material and will in turn reduce failure duration.

(Arvind Mital)
Adviser (Signal)