GOVERNMENT OF INDIA
MINISTRY OF RAILWAYS
(RAILWAY BOARD)

No.2010/M(L)/101(2) New Delhi, dated 20th November 2012

Chief Mechanical Engineers
All Indian Railways

Sub: Resetting of Alarm Disc from ground level

It is understood that all DEMUs have not been provided with Alarm Disc Resetting Wire Ropes on end body of the coaches. This is causing difficulty for LPs and Guards working on DEMU trains to reset whenever alarm chain is pulled up by passengers en route.

2. The entire population of DEMUs on your Railway may be surveyed and Alarm Disc Resetting Wire Ropes should be provided so as to enable resetting from ground level.

20.11.12

(Vivek Kumar)
Exec.Dir.Mech.Engg.(Tr)
Railway Board

Copy to: CME/ICF & Sr.EDS(MP)/RDSO